

Photo Album for Morinville, AB

Job 23223

September 24, 2010

This week your apparatus began 3rd party aerial testing and was staged to begin water way testing. Next week aerial testing should be completed and your apparatus should be released to 3rd party pump testing.





DSC00213



DSC00214



DSC00215



DSC00216



DSC00217



DSC00218



DSC00219



DSC00220



DSC00221



DSC00222



DSC00223



DSC00224



DSC00225



DSC00226



DSC00227



DSC00228



DSC00229



DSC00230



DSC00231



DSC00232



DSC00233



DSC00234



DSC00235



DSC00236



DSC00237



DSC00238



DSC00239



DSC00240



DSC00241



DSC00242



DSC00243



DSC00244



DSC00245



DSC00246